




Model XSH03Z Parts List

A = Standard Equipment

O= Circuit Diagram

Item#	Part#	Description	Q'ty	Unit
001	911263-2	PAN HEAD SCREW M5X40	1	PC.
002	265995-6	TAPPING SCREW 4X18	7	PC.
003	183A13-3	HANDLE SET	1	
	C10 263005-3	RUBBER PIN 6	2	PC.
	C20 805E02-9	CAUTION LABEL	1	
	D10	INC. 18		
004	142948-1	INDICATION PLATE COMPLETE	1	
005	650734-1	SWITCH TG73BDS-2	1	
006	231469-9	COMPRESSION SPRING 4	1	PC.
007	419664-3	LOCK OFF LEVER	1	PC.
008	231469-9	COMPRESSION SPRING 4	1	PC.
009	455480-9	SWITCH LEVER	1	
010	911263-2	PAN HEAD SCREW M5X40	3	PC.
011	455437-0	MOTOR HOUSING	1	
012	850H70-5	XSH03 NAME PLATE	1	
013	632D90-5	STATOR UNIT	1	PC.
014	644808-8	TERMINAL	1	PC.
015	632D81-6	SWITCH UNIT	1	
016	455440-1	BAFFLE PLATE	1	
017	911263-2	PAN HEAD SCREW M5X40	1	PC.
018	183A13-3	HANDLE SET	1	
	C10 263005-3	RUBBER PIN 6	2	PC.
	C20 805E02-9	CAUTION LABEL	1	
	D10	INC. 3		
019	266091-3	TAPPING SCREW 4X50	2	PC.
020	911128-8	PAN HEAD SCREW M4X16	1	PC.
021	455483-3	DUCT	1	
022	123269-0	HOOK ASSEMBLY	1	PC.
023	911233-1	PAN HEAD SCREW M5X20	2	PC.
024	142942-3	BLADE CASE COMPLATE	1	
	C10 213953-6	O RING 24	1	PC.
025	519359-9	ROTOR ASS'Y	1	PC.
	D10	INC. 26-28		
026	210022-4	BALL BEARING 626DDW	1	PC.
027	240045-8	FAN 55	1	PC.
028	210051-7	BALL BEARING 609LLB	1	PC.
029	346837-4	SHAFT LOCK	1	
030	286275-7	CAP	1	PC.
031	233117-6	COMPRESSION SPRING 6	1	PC.
032	262552-1	RUBBER SLEEVE 6	1	PC.
033	251247-1	+ PAN HEAD SCREW M6X20	1	PC.
034	266194-3	FLAT HEAD SCREW M6X90	1	PC.
035	213565-5	O RING 42	1	PC.
036	210028-2	BALL BEARING 606ZZ	1	PC.
037	961052-5	RETAINING RING S-12	1	PC.
038	227794-4	HELICAL GEAR 50	1	
039	257349-1	SLEEVE 12	1	
040	911223-4	PAN HEAD SCREW M5X16	2	PC.
041	319212-7	BEARING BOX	1	
042	211131-2	BALL BEARING 6001DDW	1	PC.

043	326459-6	SPINDLE	1
044	285845-9	BEARING RETAINER 19-29	1 PC.
045	231878-2	TENSION SPRING 4	1 PC.
046	319211-9	SAFETY COVER	1
047	961152-1	RETAINING RING (EXT) S-34	1 PC.
048	224411-7	INNER FLANGE 35	1 PC.
049	224409-4	OUTER FLANGE 35	1 PC.
050	266924-2	HEX. SOCKET HEX. BOLT M6X18	1
051	266034-5	TAPPING SCREW CT 4X16	1 PC.
052	272282-6	LEVER 60	1
053	257982-9	BOW STOP RING E-8	1 PC.
054	272272-9	LEVER 45	1 PC.
055	266735-5	HEX.BOLT M6X20	1 PC.
056	941151-9	FLAT WASHER 6	1 PC.
057	252103-8	HEX. LOCK NUT M5-8	1 PC.
058	346836-6	ANGULAR GUIDE	1
059	317986-4	STOPPER	1 PC.
060	213062-1	O RING 9	1 PC.
061	265084-7	+ TRUSS HEAD SCREW M5	1 PC.
062	256480-0	SHOULDER PIN 6-7	1 PC.
063	911203-0	PAN HEAD SCREW M5X8	1 PC.
064	455515-6	TOP GUIDE	1
065	266318-1	H.S.SET SCREW(FLAT POINT)M4X6	2 PC.
066	455517-2	BEVEL GUIDE	1
067	251896-4	SCREW M5X20	1 PC.
068	231007-7	COMPRESSION SPRING 6	1 PC.
069	253058-0	FLAT WASHER 7	1 PC.
070	256511-5	SHOULDER PIN 6-7	1 PC.
071	346835-8	DEPTH GUIDE	1
072	941151-9	FLAT WASHER 6	1 PC.
073	332126-3	PIPE 6	1
074	941151-9	FLAT WASHER 6	1 PC.
075	264103-6	HEX. NUT M6	1
076	272272-9	LEVER 45	1 PC.
077	257982-9	BOW STOP RING E-8	1 PC.
078	319210-1	BASE	1
079	266436-5	H.S.SET SCREW(FLAT POINT)M5X8	1
080	266436-5	H.S.SET SCREW(FLAT POINT)M5X8	1
081	266436-5	H.S.SET SCREW(FLAT POINT)M5X8	1
082	251896-4	SCREW M5X20	1 PC.
083	231007-7	COMPRESSION SPRING 6	1 PC.
084	266436-5	H.S.SET SCREW(FLAT POINT)M5X8	1
085	253077-6	FLAT WASHER 6	1 PC.
A01	783203-8	HEX. WRENCH 5	1 PC.
A02	A-85092	T.C.T.SAW BLADE 165X24TX15.88	1 PC.
E01	805E03-7	CAUTION LABEL	1